



Contact gauge

Version: 2011-01



mechanical, for welding machines

- pressure range from 0 up to 10 bar
- welding pressure monitoring
- Schweißstart-Freigabe durch voreingestellten Mindestdruck

Order-number: XV0.X0.024.004



digital, for welding machines

- universal sensor
- one analogue output 0-10 V
- welding pressure monitoring
- Schweißstart-Freigabe durch voreingestellten Mindestdruck
- display:
 1. working pressure
 2. min. pressure
 3. max. pressure

Order-number: XV0.X0.021.005

We reserve the right to make changes which are in the interest of technical progress.

© by WMA Schmidt & Bittner GmbH, Baumwaide 23, D-74360 Illfeld-Auenstein, Tel. +49 7062 9066-0, Fax +49 7062 9066-20
info@wma-sb.de or wma-sb@t-online.de, <http://www.wma-sb.de>

Contact gauge-1